


Exhibit B



Location of work



Aerial drone “before” photo

SITE PHOTOS

Photo 1.

Edge of 3-Acre Revegetation area on July 6th, 2021 before clearing.



Photo 2.

Regraded barren area prepared for revegetation. About 3 acres in area. Facing east toward Locust Fork.

Pile of agricultural limestone.

Photo taken on July 13th during site visit.



SITE PHOTOS

Photo 3.

July 16th after lime applied
and disked in.

Seed and fertilizer were
applied on July 20th, 2021



Photo 4.

August 2nd, 2021, with
vegetation emerging.



SITE PHOTOS

Photo 5.

August 17th, 2021 with
vegetation becoming
established.

